

From: Cain, Danielle <danielle.cain@TeamInc.com>
Sent: Thursday, April 26, 2018 4:57 PM
To: Liesch, Barbara <Barbara.Liesch@expera.com>
Subject: Expera - Thilmany 2018 LDAR Reports
Attach: Added-Deleted Summary - 2018.pdf; Components Currently Out of Service - 2018.pdf; Difficult to Monitor List - 2018.pdf; Inspection History - 2018.pdf; Master Component Detail List - 2018.pdf; Monitoring Score Card - 2018.pdf; Unsafe to Monitor List - 2018.pdf

Hello,

Please find attached the 2018 reports for Expera - Thilmany in Kaukauna, WI.

2018 LDAR Summary:

Components Monitored	Leaks Found	Late 1st Repair Attempts	Late Effective Repairs	Unrepaired Non-DOR Leaks	Components on DOR	Components Out of Service	Components Added	Components Deleted
215	0	0	0	0	0	0	0	0

Please send repair information for any un-repaired components as soon as you can.

Please review current Delay of Repair report, and inform us if any have been repaired and/or if any expected repair dates have changed.

Please review current OOS report, and update us if any components have been put back into service or have been removed.

If you require additional information or reports, please let me know.

Also, if you need any assistance with leaks, DOR repairs, and/or other support – TEAM Industrial Services, Inc. can provide the following supplementary services: Leak Repair Services, Hot Tapping Services, Field Machining, Pipe Repair Products, Valve Packing Extraction and Repacking, Field Heat Treating Services, NDT Inspection Services, Concrete Repair Services, and Energy Management Services.

Thank you,

Danielle A Cain

ECS – 1424 MSP TMS



391 Bridgepoint Way
South St. Paul, MN 55075
(651) 768-0006 Office
(651) 768-0003 Fax
Danielle.Cain@teaminc.com
www.TeamInc.com

EXP2963

ED_005481B_00000391-00001